

## - Site Service Report -

IRD SO#: 11013C IRD Ref:

From: Greg Felsing To:Cindy Mantie

**Project Name:**AZ LTTP-2

Project Location: I-10 @ MP 108.5 EB

Service Date(s):Mar.12,2009

Weather: sunny 60F

Job Description: Repair broken out section of epoxy in roadway.

Work Completed: Repaired chipped out section with Kistler grout., Check pads for

any loose areas.

Work Remaining: None at this time.

Parts Used: 1 pail of Kistler grout, leftover from a previous project in NV

Mileage / Travel Time: 42miles/3hrs

Time Spent on Site:2 hours

Notes: Epoxy is cracking, and in one place broken out of BP2 home run

## **Action Items:**

Item	Action Required	Ownership
1.		IRD





